

TECHNICAL BULLETIN #20-12-1

RS-1000 ICE RESCUE SUIT

OPTIONAL REMOVAL OF STAINLESS STEEL STUDS



Firstwatch has developed improved traction performance for the boots of the RS-1000 Rescue Suit. This has been achieved through the use of Stainless Steel Studs located at strategic locations of boot outsoles.



Some user's rescue equipment such as boats or sleds may be adversely affected by the use of studded boots during operations.

Stainless Steel studs can be quickly removed from the rubber outsoles without affecting the waterproof integrity of the boots.

Studs can be easily removed with pliers by grasping 2 studs at a time and rotate to remove. The outsole will remain waterproof and not be adversely affected by the studs removal or suit warranty.

